

09/319,478

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,314,717 B1
DATED : November 13, 2001
INVENTOR(S) : J. Michael Teets et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2,

Line 6, after "arrangement" insert period -- .--.
Line 50, "3A" should read -- 1A --.

Column 5,

Line 37, "oil pump So" should read -- oil pump 50 --.
Line 42 "electromechanical" should read -- electro-mechanical --.
Line 58, "FIGS. 3A" should read -- FIGS. 1A --.

Column 7,

Line 55, before "annular" insert -- An --.

Column 8,

Line 2, "NO_xemmissions" should read -- NO_x emissions --.

Column 10,

Line 45, "(AP)" should read -- (ΔP) --.

Column 15,

Line 3, "angle a" should read -- angle α --.
Line 46, "electromechanical" should read -- electro-mechanical --.

Column 16,

Line 40, "springloaded" should read -- spring-loaded --.

Signed and Sealed this

Fourth Day of June, 2002

Attest:



Attesting Officer

JAMES E. ROGAN
Director of the United States Patent and Trademark Office



P Cg C
PATENT

ATTORNEY'S DOCKET NO. 3419-990811

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re United States
Letters Patent of :

J. MICHAEL TEETS ET AL. :

ELECTRICITY GENERATING SYSTEM
HAVING AN ANNULAR COMBUSTOR

Patent Number 6,314,717 :

Issued – November 13, 2001 :

Examiner – E. D. Hayes :

CERTIFICATE

FEB 25 2002

Pittsburgh, Pennsylvania
January 28, 2002

OF CORRECTION

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 C.F.R. 1.322(a))

Commissioner for Patents
Washington, D.C. 20231

ATTENTION: Decision and Certificate of Correction Branch
Patent Issue Division

Sir:

In accordance with 35 U.S.C. §254, we attach hereto, in duplicate, Form
PTO/SB/44 and request that a Certificate of Correction be issued in the above-identified patent.

The following errors appear in the patent as printed:

Column 2 Line 6, after "arrangement" insert period (.).
(Application Page 2 Line 30)

Column 2 Line 50 "3A" should read --1A--.
(Application Page 4 Line 3)

Column 5 Line 37 "oil pump So" should read --oil pump 50--.
(Application Page 9 Line 11)

Column 5 Line 42 "electromechanical" should read --electro-mechanical--.
(Application Page 9 Line 17)

Column 5 Line 58 "FIGS. 3A" should read --FIGS. 1A--.
(Application Page 9 Line 34)

Column 7 Line 55 before "annular" insert --An--.
(Application Page 11 Line 19)

Column 8 Line 2 "NO_xemissions" should read --NO_x emissions--.
(Application Page 14 Lines 1-2)

Column 10 Line 45 "(AP)" should read --(ΔP)--.
(Application Page 18 Line 35)

Column 15 Line 3 "angle a" should read --angle α--.
(Application Page 27 Line 7)


Column 15 Line 46 "electromechanical" should read --electro-mechanical--.
(Application Page 28 Line 15)

Column 16 Line 40 "springloaded" should read --spring-loaded--.
(Application Page 30 Lines 4-5)

Respectfully submitted,

WEBB ZIESENHEIM LOGSDON
ORKIN & HANSON, P.C.

By



Richard L. Byrne
Registration No. 28,498
Attorney for Applicants
700 Koppers Building
436 Seventh Avenue
Pittsburgh, PA 15219-1818
Telephone: (412) 471-8815
Facsimile: (412) 471-4094

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,314,717 *B1*
DATED : November 13, 2001
INVENTOR(S) : J. Michael Teets et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2 Line 6, after "arrangement" insert period (.).

Column 2 Line 50 "3A" should read --1A--.

Column 5 Line 37 "oil pump So" should read --oil pump 50--.

Column 5 Line 42 "electromechanical" should read --electro-mechanical--.

Column 5 Line 58 "FIGS. 3A" should read --FIGS. 1A--.

Column 7 Line 55 before "annular" insert --An--.

Column 8 Line 2 "NO_xemissions" should read --NO_x emissions--.

Column 10 Line 45 "(AP)" should read --(ΔP)--.

Column 15 Line 3 "angle a" should read --angle α--.

Column 15 Line 46 "electromechanical" should read --electro-mechanical--.

MAILING ADDRESS OF SENDER:

The Webb Law Firm
700 Koppers Building
436 Seventh Avenue
Pittsburgh, PA 15219-1818

PATENT NO. 6,314,717

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,314,717
DATED : November 13, 2001
INVENTOR(S) : J. Michael Teets et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 16 Line 40 "springloaded" should read --spring-loaded--.

MAILING ADDRESS OF SENDER:

The Webb Law Firm
700 Koppers Building
436 Seventh Avenue
Pittsburgh, PA 15219-1818

PATENT NO. 6,314,717

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,314,717
DATED : November 13, 2001
INVENTOR(S) : J. Michael Teets et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2 Line 6, after "arrangement" insert period (.).

Column 2 Line 50 "3A" should read --1A--.

Column 5 Line 37 "oil pump So" should read --oil pump 50--.

Column 5 Line 42 "electromechanical" should read --electro-mechanical--.

Column 5 Line 58 "FIGS. 3A" should read --FIGS. 1A--.

Column 7 Line 55 before "annular" insert --An--.

Column 8 Line 2 "NO_xemissions" should read --NO_x emissions--.

Column 10 Line 45 "(AP)" should read --(ΔP)--.

Column 15 Line 3 "angle a" should read --angle α--.

Column 15 Line 46 "electromechanical" should read --electro-mechanical--.

MAILING ADDRESS OF SENDER:

The Webb Law Firm
700 Koppers Building
436 Seventh Avenue
Pittsburgh, PA 15219-1818

PATENT NO. 6,314,717

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,314,717
DATED : November 13, 2001
INVENTOR(S) : J. Michael Teets et al.

It is certified that error appears in the above-identified patent and that said Letters Patent
is hereby corrected as shown below:

Column 16 Line 40 "springloaded" should read --spring-loaded--.

MAILING ADDRESS OF SENDER:

The Webb Law Firm
700 Koppers Building
436 Seventh Avenue

Pittsburgh, PA 15219-1818

PATENT NO. 6,314,717

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.